

From: [Sanchez, Carlos](#)
To: [Meyer, John](#)
Cc: [Miller, Garyg](#); [Leos, Valmichael](#)
Subject: San Jacinto Update
Date: Tuesday, March 22, 2016 2:30:10 PM

The rock placement is going well. They completed three areas and should finish tomorrow.
The security camera placement hit a snagged. The poles for the camera placement were shorter than the specification.

Carlos A. Sanchez
Chief, Superfund AR/TX Section
214-665-8507
Sanchez.carlos@epa.gov



9769045